Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	57	(galvanizing near5 line).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 12:35
S3	30	oxidiz\$5 near2 (treatment environment) with (heat\$3 anneal\$3) and galvaniz\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 14:47
S6	189	(oxidiz\$5 oxidation) with (heat\$3 anneal\$3 ".deg.") and galvaniz\$5 and reduc\$4 with furnace	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 14:48
S5	157	oxidiz\$5 with (heat\$3 anneal\$3 ". deg.") and galvaniz\$5 and reduc\$4 with furnace	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 14:48
S7	177	S6 not S4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 14:50
S8 .	3	S7 and residence adj time with temperature with control\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 14:57
S10	11	mignard near2 francois	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; ·IBM_TDB	OR	ON	2007/03/01 15:30
S12	. 3	S10 and mov\$3 near5 furnace	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 15:31

			· · · · · · · · · · · · · · · · · · ·	<del> </del>		
S11	1	S10 and moving near3 furnace	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 15:31
S9	19	S7 and time with temperature with control\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 15:34
S4	104	(oxidiz\$5 oxidation) near2 (treatment environment) with (heat\$3 anneal\$3) and galvaniz\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 15:34
S14	57	S13 not (S4 S7)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 15:35
S15	8	S13 and moving near5 furnace	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 15:37
S16	2	S13 and moving near5 (oxidiz\$5 oxidation)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/03/01 15:39
S17	1	S13 and (moved moves) near5 (oxidiz\$5 oxidation)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 15:40
S19	26	(S4 or S6) and (moved moves moving) near5 furnace	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 15:45

010		(64 - 65) - 17	110 000117	i i i		2007/00/5: := :=
S18	4	(S4 or S6) and (moved moves moving) near5 (oxidiz\$5 oxidation)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 15:45
S21	390	S4 S6 S13 S20	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/03/01 16:05
S20	77	(oxidiz\$5 oxidation) near2 (heater chamber compartment means housing) and galvaniz\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 16:05
S22	19	S21 and line adj speed with temperature	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 16:26
S25	40	S21 and (oxidiz\$3 oxidation) with temperature with (time speed)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 16:27
S24	101	S21 and (oxidiz\$3 oxidation) same temperature with (time speed)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 16:27
S23	142	S21 and (oxidiz\$3 oxidation) same temperature same (time speed)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/01 16:27
S13	130	(oxidiz\$5 oxidation) near2 (furnace) and galvaniz\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/05 11:49

L4	17	3 not 2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/05 12:01
L3	25	(oxidiz\$5 oxidation) same reduc\$3 same (modif\$4 adjust\$4 chang\$4 control\$4) with (gap distance length) and galvaniz\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OŖ	ON	2007/03/05 12:01
L2	12	(oxidiz\$5 oxidation) same reduction same (modif\$4 adjust\$4 chang\$4 control\$4) with (gap distance length) and galvaniz\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/05 12:01